

ABSTRACT

In order to provide a superconducting wire that has a high critical current value, has no defects such as bulges, and has high mechanical strength, an
5 oxide superconducting material (1) is covered, and ceramic particles or fibers
(3) are buried in the surface of a covering (2) made of metal

FIG. 2